



SAFETY INFORMATION

1/18

Update to BPA Safety Notice 1/99 (TSE Zerox Containers)

Safety Notice 1/99 requires the fitting of a protection flap to ALL Vector and Zerox containers used for static line parachuting. This was due to the possible extraction of the curved pin used to close the reserve container.

This safety notice did not affect equipment that used a straight reserve pin such as Javelin or Telesis containers

Later designs of the Zerox container now use a straight pin.

At the Riggers Sub Committee meeting of the 1st February 2018 it was agreed that Zerox containers should only be subject to this safety notice when fitted with the older style curved pin and RSL.

Those of the newer, straight pin design, do not require the addition of the protector flap as per SN 1/99.

2nd February 2018

Distribution

CIs
Council
Riggers
STC Mailing
Skydive – The Mag
File